

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**


PATENT NO. : 7,349,226 B2  
APPLICATION NO. : 10/638982  
DATED : March 25, 2008  
INVENTOR(S) : Ice

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**Drawings**

Sheet 1, replace Figure 1 with the figure depicted below, wherein the connectors 306 have been relabeled 312




Signed and Sealed this


Fourteenth Day of September, 2010

David J. Kappos  
Director of the United States Patent and Trademark Office

Sheet 2, replace Figure 2 with the figure depicted below, wherein the channel 404G has been relabeled 404A



Sheet 6, replace Figure 4B with the figure depicted below, wherein the channel 404B has been relabeled 404A and the channel 402B has been relabeled 404A



**Column 6**

Line 15, after “**400**”, add [(see FIG. 2)]  
Line 33, after “**300**”, add [(see FIG. 1)]

**Column 8**

Line 5, change “**302**” to **--302A--**  
Line 10, change “**302**” to **--302A--**  
Line 46, change “**304**” to **--302--**  
Line 60, after “**100**”, add [(see FIG. 2)]  
Line 63, change “**1100**” to **--100--**

**Column 10**

Line 30, after “**100**”, add [(see FIG. 4A)]  
Line 40, change “**3101B**” to **--310B--**  
Line 40, change “**3101B**” to **--310B--**

**Column 11**

Line 6, after “**302**”, add [(see FIG. 4A)]